

State of Nebraska Underground Storage Tank Summary Information

Reporting Period: October 1, 2008 to September 30, 2009

This report has been prepared pursuant to EPA's Public Record UST Grant Guidelines.

Questions about the General Information and On-Site Inspections may be addressed to the State Fire Marshal's Office at 402-471-9465.

Questions about Confirmed Releases may be addressed to the Department of Environmental Quality Petroleum Remediation Section at 402-471-2186. For a list of "Leaking UST and Surface Spill Sites" see NDEQ's website at www.deq.state.ne.us under Programs/Petroleum Remediation/LUST & Surface Spill Site Information.

Date Posted: December 1, 2009

General Information

Total Number of UST Facilities: 2606
Total Number of USTs: 6912

On Site Inspections

UST Facilities Inspected: 618

Percentage of Facilities Inspected Found To Be In Compliance 47%
(With Release Detection *and* Release Prevention Regulations)

Releases

of Confirmed UST Releases: 41

Leak Autopsy Report

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	10	24.39%							7		1				2	
Piping	10	24.39%	1				2		1		2				4	
Dispenser	9	21.95%	5												4	
Submersible Turbine Pump																
Delivery Problem	4	9.76%			4											
Other (e.g. unknown)	8	19.51%													8	
Totals	41	100%	6		4		2		8		3				18	